Investigation and Rehabilitation of a Bridge Abutment MSE Wall Instability

Marshall B. Addison Ph.D., P.E. Geotechnical Consultant

© Geosynthetics Conference

1

KEY POINTS

As a designer, always evaluate if "new" geo solutions have been properly vetted before relying upon industry developed specifications.

KEY POINT

As a designer or builder, always consider long-term compatibility of reinforcement and retained soil materials used to construct infrastructure

3

Investigation and Rehabilitation of a Bridge Abutment MSE Wall Instability

First contacted in July 2001
Large city engineering
department had an ongoing
settlement problem of
embankment at
approach/departure bridge slab
MSE wall built in 1985

















Investigation begins with no info on MSE wall design

13


```
Built 1985
Engineering letter reports:
1989
1991
1994
Our investigation 2001
```





























Literature review and engineering analysis

Some details of MSE wall are found in Public Works Dept.

27

Built 1985

Pressure grouting to lift settled approach slabs:

1989

1991

1994

Our investigation 2001

STATE DEPARTMENT OF HIGHWAYS AND PUBLIC TRANSPORTATION

SPECIAL SPECIFICATION 3

ITEM 4002

RETAINED EARTH WALLS

.1. Description. This item shall govern for the construction of Retained Earth Walls in accordance with these specifications and with the lines, grades and dimensions shown on the plans.

29

All backfill material used in the structure volume shall be free from organic or otherwise deleterious materials and shall conform to the following gradation limits as determined by Test Method Tex-110-E.

Sieve Size

Percent Passing

6 inches 3 inches 100 75 - 100

The Resistivity shall be 1,500 ohms-cm or greater as determined by Test Method Tex-129-E.


The pH range shall be from 5.5 to 9.0 as determined by Test Method Tex-128-E.

Materials not meeting these gradation limits may be used if they conform to the following additional requirements:

- The fraction finer than the No. 200 sieve as determined by Test Method Tex-100-E shall not exceed 25 percent.
- The Plasticity Index (P.I.) as determined by Test Method Tex-106 shall not exceed 6.
- The material, when compacted to 95% density as determined by Test Method Tex-114-E at optimum moisture content, shall exhibit an angle of internal friction of not less than 34 degrees as determined by Test Method Tex-117-E.

SS 3

2-7




Select Granular Fill Material for the Reinforced Zone of Walls. All fill material used in the structure volume for MSE wall structures should be reasonably free from organic or other deleterious materials and should conform to the gradation limits, PI and soundness criteria listed in Table 3-1. Note that Table 3-1 presents a broad gradation range that is applicable across the United States. Individual DOTs may adjust this range based upon locally available and economical select granular fill. The reinforced fill should be well-graded in accordance with the Unified Soil Classification System (USCS) in ASTM D2487. Unstable broadly graded soils (i.e., $C_u > 20$ with concave upward grain size distributions) and gapgraded soils should be avoided (see Kenney and Lau, 1985, 1986 for a method to identify unstable soils). These soils tend to pipe and erode internally, creating problems with both loss of materials and clogging of drainage systems.

3 - 2


FHWA NHI-10-024 MSE Walls and RSS – Vol I 3 – Soil Reinforcement Principles November 2009


Gradation: (AASHTO T-27)	U.S. Sieve Size	Percent Passing(a)
	4 in. (102 mm) ^(a,b)	100
	No. 40 (0.425 mm)	0-60
	No. 200 (0.075 mm)	0-15
Plasticity Index, PI (AASHTO T-90)	PI ≤ 6	
Soundness: (AASHTO T-104)	The materials shall be substantially free of shale or other soft, poor durability particles. The material shall have a magnesium sulfate soundness loss of less than 30 percent after four cycles (or a sodium sulfate value less than 15 percent after five cycles)	





Performance and calculations revealed pullout failure of bar mat reinforcement

35









Options to consider for remediation

Phase II investigation recommended sodium silicate permeation grouting program to increase passive resistance of in-place reinforcement to keep route open to hospital district

41

Interviewed and selected a Geotechnical specialty contractor

Determined DCP with extensions would be an economical means on the slopes to evaluate current and after grouting in-place stiffness




















Statistical analysis of Deep DCP testing revealed, on this project, that injections spaced greater than 54" (1.4m) encountered significant deterioration in after grouting stiffness.

Closer spacings of DDCP probes
Found uniform resistance that
was approximately 3.5 X
stiffer than pre permeation
grouting results and resulted in
F.S. exceeding 1.5 at all locations


53





Specifications were developed


The grouting sequence did not allow injections next to fresh grout

55











The wall was surveyed during initial injections to monitor wall movements as the fluid grout initially reduced pullout resistance before setting up.





LESSONS LEARNED

As a designer, always evaluate if "new" geo solutions have been properly vetted before relying upon industry developed specifications.

63

LESSONS LEARNED

As a wall designer, always consider long-term compatibility of reinforcement and retained soil materials used to construct infrastructure

